## **Price Sheet/Check list**

Rev.01/17

The following costs are base costs for work that is done from 8:00am -5:00pm Monday thru Friday. If the maintenance repair is an after hours emergency call, and the damages are a direct result of tenants actions, then there will be an additional \$30 charge applied to the cost below.

Item	Cost	<u>Item</u>	Cost	
Locks		Roach Treatment (Min.)	\$65.00	
1 Lock changes 1 Door	\$50.00	Lockout		
After hours	\$75.00	During work hours	\$25.00	
2 Locks changes 1Door	\$75.00	After hours	\$50.00	
After hours	\$100.00	Plumbing		
If locks are change & lost	\$150.00	Drain Opening (Min.)	\$75.00	
<b>Door Replacement Only</b>		Toilet Opening	\$50.00	
Interior Door (hollow core)	\$75.00	Replacement Toilet Sit	\$15.00	
Exterior Door	\$150.00	Replace toilet	\$150.00	
Bi-fold Door (per door)	\$50.00	Replace Toilet Tank	\$60.00	
By-pass Door (per door)	\$50.00	Replace Toilet lid	\$30.00	
Door and Frame Replacement		Drywall Repair/Paint		
Interior Door (hollow core)	\$100.00	Repair hole	\$35/sq.ft.	
Exterior Door	\$150.00	Re-Paint room	\$150.00	
Bi-fold Door (per door)	\$100.00	Carpet Damage		
By-pass Door (per door)	\$100.00	Replace Carpet	\$25/sq. yd.	
Storm Door Replacement	\$125.00	Clean Carpet (Min.)	\$75.00	
Hole in Door (Quarter size)	\$25.00	Electrical		
HVAC		Outlet, Switch Covers	\$5.00 each	
New Thermostat	\$50.00	Replace Outlets	\$5.00	
Furnace Filter	\$10.00	Replace Switches	\$5.00	
Kitchen Cabinets		Light globe	\$10.00	
Drawer Replacement	\$50.00	Light Fixture (Min.)	\$15.00	
Door Replacement	\$50.00	Light Bulb	\$2.50	
Handle Replacement	\$5.00	Smoke Alarm Replacement	\$35.00	
Screens		Ceiling Fan Replacement	\$75.00	
New screen and frame	\$50.00	Fire Extinguishers		
Replace screen only	\$30.00	Recharge	\$60.00	
Window Glass Replacement		New	\$100.00	
Storm window glass (Min.)	\$50.00	Exterior		
Single Window Glass (Min.)	\$75.00	Mailbox	\$30	
Double Window Glass (Min.)	\$100.00	Appliance		
Window and Frame Replacement		Clean Stove	\$50.00	
New storm window (Min.)	\$85.00	Clean Refrigerator	\$50.00	
Wood Replacement Frame (Min.	) \$100.00	<b>Cleanness of Unit at Move of</b>	out will	
Vinyl Replacement Frame (Min.)	\$150.00	be anything between \$75 to	\$200 if	
Window Blinds		<b>Cornerstone does the cleaning</b>	g.	
Horizontal blinds under 48"	\$15.00		8	
Horizontal Blinds Over 48"	\$60.00	And, any other costs incur	red by	
Vertical Blinds	\$75.00		Cornerstone of Topeka, due to "tenant	
Vertical Blind strips (Each)	\$5.00		damage" will be charged according to	
Debris/ Junk/Bugs			material cost plus time at \$30/hour.	
Debris/ Junk Removal \$25/hr		muci an cost pius unic di \$50/no	<del></del>	
Pickup load \$100.00	)			

\*\* MISSING APPLIANCES WILL BE CHARGE AS NEW\*\*

Tenant initials \_\_\_\_\_